

QUARZO PLUS

Rev.01/2019

DESCRIPTION

Quartz paint for interiors and exteriors, good coverage, wash resistance and breathability.
Granulometry max: 0.05 mm.

USES

It is ideal for achieving an even and matt finish. Generally suitable for use on old and new civil lime or cement-based plasters.

PREPARING THE SURFACE

Ensure the surface is perfectly dry and well-seasoned (4-6 weeks), levelled, smooth and finely sanded, free of flaky and oily residues, efflorescence, vegetation and bacterial contaminants.

New bases: Brush and dust to remove all impurities, fill properly if necessary, and impress with suitable, properly diluted SOLVEX OR CLK fixatives.

Old or chalking bases, or in any exteriors: Brush and dust to remove any flaking part, fill properly if necessary, and finally consolidate with SOLVEX or with suitable, properly diluted water-based topcoats.

NOTE: In the case of surfaces that are particularly flaky or that have been treated with mortars and/or plasters, before proceeding with finishing coats, wait for complete drying (15-30 days under optimal environmental conditions), then prime with appropriately diluted SOLVEX.

APPLICATION

Apply at least two coats of QUARZO PAINT by brush, roller or spray. Allow at least 18 hours after the primer and at least 8 hours between the first and second coat of paint. Apply between temperatures of 5 and 30°C. Do not apply on surfaces that are in direct sunlight, hot or cold, or in the presence of strong wind, if rain is imminent or in the presence of high relative humidity. Stir well before use.

DILUTION

Add 15-20% water.

TECHNICAL DATA

PRODUCT
SPECIFIC WEIGHT
VISCOSITY
pH
GLOSS

Quartz paint for interiors and exteriors
1.610 ± 0.050 kg/L
42000 ± 5000 Brookfield cPs at 23 °C.
7-9
opaque <10 G.U. 85°

COLOUR

White and chart colours

RECOMMENDED THICKNESSES

60 to 70 dry microns per coat

NUMBER OF COATS RECOMMENDED

2 coats

RE-COATING

8-10 hours

APPLICATION METHOD

brush, roller or spray

THEORETICAL YIELD:

3-4 sqm/l for 2 layers

DRYING TIME (at 23 ° C)

Touch dry

1-2 hours

Deep dry

18-24 hours

CLEAN TOOLS

With water immediately after use.

STORAGE

Keep away from heat, in a cool and ventilated place, protected from chills.

The above technical knowledge regarding the application and the proper use of the products does not mean ALCAS ITALIA s.r.l. assumption of responsibility for the use and application of the products. Because of the unpredictable variability of operating conditions, the APPLICATOR must verify the use of the product under their own conditions with direct evidence. We reserve the right to change the contents of this document without prior notice. As soon as a new version of this data sheet is available, it will no longer be valid.